(JAPAN)


OMRON

# 形G3J-T 形G3J-S 形G3J


ソリッドステートコンタクタ

# 取扱説明書

オムロン製品をお買いあげいただきありがとうございます。 この製品を安全に正しく使用していただくために、お使いになる前にこの取 扱説明書をお読みになり、十分にご理解してください。



(カタログ番号SDRR-305)の注意事項をあわせてご覧ください。



# オムロン株式会社

0622052-0F

## 安全上のご注意

#### ●警告表示の意味

誤った取り扱いをすると、死亡または重傷を負う可能性が 想定される場合を示します。



誤った取り扱いをすると、傷害を負う可能性が想定される場 合、および物的損害の発生が想定される場合を示します。

#### ●警告表示

配線をおこなう場合には必ず電源を切った状態でおこなってください。 また通電中はカバーを取り付けた状態で使用してください。 感電の恐れがあります。



通電中や電源を切った直後はSSR本体、放熱フィン部には触らないでください。 本体および放熱フィン部は高温になっているため、やけどの原因になります。

電源を切った直後に出力端子に触れないでください。 内蔵スナバ回路に電荷が充電されているため感電の原因となります。

SSR本体、放熱器周囲の空気の対流を妨げないでください。 本体の異常発熱により出力素子のショート故障、焼損の原因となります。

SSRの負荷側に短絡電流が流れないようにしてください。 短絡電流が流れた場合、SSRが破裂する場合があります。




・当社は、品質・信頼性の向上に努めておりますが、SSRには半導体を使用しており、半導体は一般的に誤 動作したり、故障することがあります。SSRをご使用頂く場合には、SSRの故障によって結果として、人身 事故・火災事故・社会的な損害を生じさせないよう安全を考慮した、システムとしての冗長設計・延焼対策 設計・誤動作防止設計などの安全設計に十分ご留意ください。

・形G3Jの操作回路・主回路に渦雷圧・渦雷流を印加しないでください。形G3Jの故障および焼損の原因


・出力端子のねじが緩んだ状態で使用しないでください。端子部の異常発熱により快損の原因になります。

## 正しい使い方

# ●取りつけ方法について



サーマルリレーの一体取りつけについて 形G3Jはオムロン製サーマルリレー形J7TM テレメカニックサーマルリレー形LR2Dを直 接取りつけられる構造となっています。 取りつけ方法は下図を参考にしてください




①サーマルリレーのフックを形G3Jのサーマルリレー取りつけ金具に引 っ掛けてください。

②あらかじめゆるめておいた形G3.Iの出力 端子にサーマルリレーの3 本のリード部分を挿入して再度、形G3Jの出力端子のねじをしめつけて

#### ●制御盤への取り付け

密閉された盤ですとSSRから発生した熱が内部にこもり、 SSRの通電能力が低下するばかりか、他の電子機器にも悪影響を与えます。 必ず盤の上部と下部に通風用の穴を設けてご使用ください。


### (1)SSRの取り付け間隔



対策室(1)

#### (2) SSRとダクト(又は空気の流れをさまたげるもの)の関係

#### ダクト(又は空気の流れを さまたげるもの) 奥行



奥行方向をダクトで覆ってしまうと 放熱が悪くなります。

奥行きの短いダクトを 使用して空けてください。 注()内寸法

形G3J-□217BL

ダクトを短くできない場合は 台座(金属製)を設けて、 SSRをダクトで覆わないようにします。


排気口

SSR

軸流ファ

対策案(2)

#### (3)制御盤外への換気



※吸気口あるいは排気口がフィルタ付きの場合、目詰まりによる効率低下を防ぐために定期的 な清掃を行ってください。

※吸気口や排気口の内、外の周辺は吸気・排気の障害となるような物を置かないようにしてくだ

※熱交換器使用時は、SSR前面の位置に取り付けるほうが効果的と思われます。

#### SSRの周囲温度を下げる。

※定格電流はSSRの周囲温度40℃での値です。

#### (一部25℃の機種もあります。)

SSRは、半導体素子で負荷を開閉していますので、通電により発熱し盤内温度も上昇します。 この発熱を制御盤にファンを付加し換気する事で、SSRの周囲温度を下げると信頼性が向上します。 (10℃の温度低減で、期待寿命が2倍になると言われています。:アレニウスの法則)

SSRの定格電流(A)	3A	5A	11A	17A
SSR1台当りのファンの数	0.14台	0.23台	0.51台	0.79台

#### 2素子タイプ

SSRの定格電流(A)	5A	11A
SSR1台当りのファンの数	0.16台	0.34台

例:3素子11AのSSR10台だと、0.51×10=5.1→ファンが6台必要です。 ※ファンの大きさ:92,風量:0.7m3/分,盤の周囲温度:30℃で算出。

#### ※同一盤内、他機種からの発熱は、別途換気が必要です。 ●ソフトスタートタイプ・ソフトスタート/ストップタイプの電源供給について

ソフトスタートタイプ形G3J-S□およびソフトスタート/ストップタイプ形G3J-T□の操作入力はソフトスタート動作およびソフト ストップ動作を安定して行うため十分電源が安定してから行ってください。

#### ●配線について

リード線の太さは電流値にあったものを使用してください。

3素子、2素子ともOFF状態でも出力端子T1、T2、T3端子は充電部となっており感電する場合があります。電源から切り離す ため上位にブレーカーなどを設置してください。2素子タイプはL2-T2間が内部で短絡されているので、L2を電源の接地側に 接続してください。L2を接地側以外に接続する場合にはモータの端子など充電部に感電・地絡を防ぐカバーなどを設けてくだ さい。高圧・動力線と形G3Jの配線を同一配管、あるいはダクトで行うと誘導を受け、誤動作または破損する場合があります。 別配管としてください。形G3J-S/形G3J-Tタイプは、3相モーターの正逆運転に使用できません。LOAD端子間にダイオード を接続しているため、相間短絡となります。

#### ●機器の保護について

より安全にお使いいただくために、右図のように、形G3Jの上段にコ ンタクタなどでラインを遮断することにより、さらに安全性が向上しま

#### ●各種ねじの締め付けについて

ユニットの各種ねじは、誤動作などの原因にならないように規定の締 め付けトルクにて締め付けてください。

締め付けトルク 1.0N・m~1.4N・m

#### ●使用条件について

定格電流以上の電流は通電しないでください。異常発熱の原因となります。 自己発熱による周囲温度の上昇に気をつけてください。特に盤内取りつけ の場合は外気との換気が十分おこなえるようファンを取りつけてください。

#### ●使用環境および保管環境について

下記の場所での使用および保管は故障や誤動作、特性劣化の原因と なりますので避けてください。

直射日光の当たる場所。

周囲温度が-20~60℃の範囲を超える場所での使用

相対湿度が45~85%RHの範囲を超える場所、湿度変化が急激で結露するような場所。 周囲温度が-30~70℃の範囲を超える場所での保管。

腐食性ガスや可燃性ガスのある場所。 塵埃、塩分、鉄粉が多い場所。

本体に直接振動や衝撃が伝わる場所 水、油、薬品などの飛沫がある場所。

#### ●清掃について

シンナー類は製品表面を溶かしたり、変色させたりしますので絶対に使用しないでください。清掃は市販のアルコールをご使用くだ


#### ●取り扱いについて

製品を落下させたり、異常な振動や衝撃を加えないでください。故障や誤動作の原因となります。

取りつけ穴加工寸法

#### ●外形寸法

## ●接続例



形G3J




リーダ抵抗を接続してください



信頼性を高める形G3Jの使用法について

この度はオムロンのソリッドステートコンタクタ形G3Jをご購入いただき有難うございます。 この商品を使用しモーターの正転/逆転運転をされる場合、下記内容につきご配慮してい ただきますよう、お願い申し上げます。

## ●形G3J(単機能タイプ)を使用する場合



## <注意事項>

1.必ず、ヒューズ、NFブレーカなどの保護機器を 併用してください。

2.正転と逆転の間にインターバルを100ms以上 とってください。入力への雑音などで誤って形 G3Jが動作した場合、相間短絡となります。

3.短絡事故を防ぐために保護抵抗Rを挿入して Rの計算式は下記参照ください。

[ 形G3J-205BLの例] 形G3J-205BLの投入電流耐量は150Apeakなので R>200V×√2 /150A≒1.9Ω


となります。なお、Rは回路電流、通電時間などを 老慮して、消費電力の小さくなる側に入れてください。 また、Rの消費電力は下記の式より求めてください。

 $P=I^2RX$ 安全係数 (I=負荷電流、R=保護抵抗、安全係数=4)

形 式	適用モータ	Rの目安
G3J-205BL (-2)	0.75kW	2Ω 100W
G3J-211BL (-2)	1. 5 kW	1Ω 200W
G3J-211BL (-2)	2. 2 kW	1Ω 400W

形G3J-S,G3J-Tタイプでは、2台使用しての I 正転/逆転運転はできません

#### ●形G3J-S,G3J-Tを使用する場合 (機械式インタロック内蔵可逆コンタクタを用いた回路)



1. 必ずヒューズ、NFブレーカなどの保 護機器を併用してください。

2.正転/逆転の切り替えはコンタクタ でおこない、100ms後に形G3J-S の入力が入るようにしてください

となります。 形G3J-Tのランプダウン時間の調整 範囲の上限は約25秒ですので、初期 シーケンスではタイムラグ25秒に設 定し、調整手順にしたがってください シーケンス回路のタイムラグは実機 に合わせ調整してください。

ンタクタのオフにはタイムラグが必要

## ●EMIについて

・この商品は「classA」(工業環境 商品)です。住宅環境でご利用され ると、電波妨害となる可能性があり ます。その場合には電波妨害に対す る適切な対策が必要となります。

#### ご使用に際してのお願い

次に示すような条件や環境で使用する場合は、定格、機能に対して余裕を持った使い方やフェールセイフなどの安全対策へ の配慮をいただくとともに、当社営業担当者までご相談くださるようお願いいたします。

①取扱説明書に記載のない条件や環境での使用。

②原子力制御・鉄道・航空・車両・燃焼装置・医療機器・娯楽機械・安全機器などへの使用。

③人命や財産に大きな影響が予測され、特に安全性が要求される用途への使用。

#### ●商品に関するお問い合わせは下記までご連絡ください。

# オムロン株式会社 営業統轄事業部

〒141-0032 東京都品川区大崎1-11-1 ゲートシティ大崎ウエストタワー14F 札幌支店/011-271-7821 北関東営業部/048-647-7554 北陸支店/076-233-5000 大阪支店/06-6282-2472 東北支店/022-265-0571 東京営業部/03-3779-9031 名古屋支店/052-561-0167 中四国支店/082-247-0228

東京支店/03-3779-9031 甲信支店/0263-32-6561 静岡支店/054-253-6181 九州支店/092-414-3211

●制御機器についての技術的なお問い合わせは下記をご利用ください 三島/TEL 0559-82-5000 東京/TEL 03-3493-7091 大阪/TEL 06-6253-0471

〈地区別に受信いたしますが、回線状況により他地区へ転送させて頂くことがあります。〉 営業時間:9:30~12:00/13:00~17:00 営業日:土・日・祝祭日および年末年始・春期と夏期の休業日を除く

■ TAAL-LA GOIDIN 16-17-14 下記でと利用 ハことい。

「オカートストンタ お客様相談課 FAX 0559-82-5051 http://www.omron.co.jp/ib-info/support/ 最寄りの各支店、営業所へご相談人ださい。

ソフトスタート/ストップタイプ 形G3J-T217BL 形G3J-T211BL 形G3J-T205BL 3∮AC200~220Vまたは3∮AC380~400V 形G3J-T405BL 形G3J-T405BL

ランブダウン時間設定ボリウム(形G3J-Tのみ 注) この数値はG3J- 1217BLにおける寸法です。

# ●規格は下記で認定されています。

定格衝撃耐雷圧……4kV 1.2×50 us 負荷短絡の場合は製品が破壊されます。

配線用電線サイズ…AWG16

# ・使用カテゴリー……G3J-S:IEC947-4-2 From 2

0 0 0 0

36.8 (注) 26.8



# OMRON


# Model G3J-T/G3J-S/G3J

**SOLID-STATE CONTACTOR** 

# HANDLING MANUAL

Thank you for purchasing an OMRON product. Confirm product which must be required and read this manual thoroughly for correct use before actually using it.

This manual should be ready to use any time whenever required.



# **OMRON Corporation**

# Safety Precautions

Definition of Precautionary Information



A potentially hazardous situation by misuse, could result n death or serious injury, or minor or moderate injury.



A potentially hazardous situation by misuse, may result inproperty damage only accident.

Warnings and Cautions

# WARNING

When ready for wiring, the power source should be disconnected first. Further, at operating this unit, the terminal cover should be closed correctly in order to prevent an electrical shock.





## Caution


Right after cutting power source or at operating, never touch SSR especially the heatsink which must be in high temperature at the surface, in order to prevent a burnt in the hand.



Do not touch the output terminal immediately after you turn off the power switch. Otherwise, electric shock may be caused because electricity is charged in the built-in snubber circuit.









#### NOTICE

The manufacturer has been making efforts to improve the product quality and reliability. But the semi-conductors used in the SSR may malfunction or get damaged When Setting up your system with the SSR, keep in full mind safety factors, such as redundant configuration, fire hazard measures and foolproof design, in order to avoid personal injury, fire and property damage

Do not apply any excessive voltage or current to the input or output circuit of the G3J. Doing so may result in damage to the G3J or cause a fire. Do not use the G3J with its output terminal screws loosened. Doing so will cause the output terminals to

generate excessive heat and burning may result.


Make sure that the G3J is well ventilated, otherwise the G3J in operation will generate excessive heat

and the output elements of the G3J may short-circuit or burning may result MOUNTING



Directly Mounting Thermal Overload Relays


Thermal Overload Relays can be directly mounted to the G3J.Refer to the following




- 1. Loosen the output terminal screws of the G3J and put the hook of the therminal overload relay on the bracket of the G3J.

  2. Insert the three leads of the therminal overload relay into the
- output terminals and tighten the output terminal screws.

If SSRs are mounted inside an enclosed panel, the radiated heat of the SSR will stay inside, thus not only dropping the carry-current capacity of the SSRs but also adversely affecting other electronic device mounted inside. Open some ventilation holes on the upper and lower sides of the control panel before use. The following illustrations provide a recommended mounting example of SSRs. They provide only a rough guide.



# (2) Relationship between SSRs and Ducts



Do not surrounded the SSR direction, or otherwise the heat radiation of the SSR will be adversely affected.


width is half as depth of SSR Use a short duct in the

) indicate type G3J- 217BL

# If the height of the ducts

cannot be lowered, place the SSRs on a metal base so that they are not surrounded by the ducts.

## (3) Ventilation



If the air inlet or air outlet has a filter, clean the filter regularly to prevent it from clogging and ensure an efficient flow of air. Do not locate any objects around the air inlet or air outlet, or otherwise the objects may

obstruct the proper ventilation of the control panel. A heat exchanger, if used, should be located in front of the SSR

Units to ensure the efficiency of the heat exchanger

## Please reduce ambient temperature of SSR

\* The rated load current value of SSR is measured at ambient temperature of 25°C or 40°C

As SSR use a semiconductor in the output element, a temperature of control panel inside ascend as heating by the passage of electric current through load. For this heating restrict, by attaching a fan to a control panel (ventilation outlet or air inlet) and doing a ventilation, an ambient temperature of SSR drop, a reliability improves.(generally,each 10°C reduction in temperature will double the expected life.)

3 - element devices

load current(A)	3A	5A	11A	17A
the required number of fan a per-unit of SSR	0.14	0.23	0.51	0.79

#### 2 - element devices

load current(A)	5A	11A
the required number of fan a per-unit of SSR	0.16	0.34

EX.: If it is 10 units of SSR for 11A (3 - element devices), 0.51×10=5.1→fan are necessary 6 units.

\*size of fan :92mm□, the volume of air :0.7m³/min., an ambient temperature of the control panel :30°C

\*For heating with a instruments except SSR ,of similar control panel inside separately a ventilation is necessary

■ Regarding the soft-start and soft-start/stop power Supply The soft-start operation of the G3J-S□ as well as the soft-start and soft-stop operation of the G3J-T□ should be made after the power supply has been stabilized fully.

#### ●In Terms of Wiring

The wire guage should be used according to the current supplied. Even if both 3-element and 2element devices are in the OFF state, the output terminals, T1, T2, are T3, are operated under the charging conditions. Therefore, you might receive electric shocks. A circuit breaker may be installed in order to isolate the current above the device.

The L2 is to be connected to the ground of the power supply because the L2 and T2 are short-circuited regarding the 2-element devices. Where this is connected to other than the ground, the protective cover must be installed in order to avoid the electric shocks or short-circuit around the charging area such as motor terminals. When the wiring of the high-voltage power lines and G3J lines is made in the same electrical conduit or duct, the electrical induction might be induced or

the misoperation or damage might be induced by the electrical induction. The saperate wiring must be needed. G3J-S/G3J-T is not available for 3 phase's motor for Forward-Reverse application. Because the output device

is used with a diode, a short-circuit is caused between the phases System Protection The systems will be safer by inserting a contactor into the power line of the G3J to shut off power supply to the G3J as shown in

#### he following diagram. Tightening Screw

Tightening each screw of the G3J securely so that the G3J will not malfunction.

Appropriate tightening torque: 1.0N·m~ 1.4N·m

#### Operating Conditions

Make sure that no current exceeding the rated current will flow into the G3J otherwise the G3J may generate excessive heat.

Make sure that there is no excess ambient temperature rise due to the heat generation of the G3J If the G3J is mounted inside a panel, install a fan to ventilate the interior of the panel properly.

Operating and Storage Environment

Do not operate or store the G3J under the following conditions

Doing so may result in damage to the G3J or cause the G3J to malfunction. Operation or storage in places with direct sunlight.

Operated in places with ambient temperature ranges not within -20°C to 60°C

Operated in places with rapid temperature changes resulting in condensation or relative humidity Storage in places with ambient temperature ranges not within -30°C to 70°C

Operation or storage in places with corrosive or inflammable gas.

Operation or storage in places with excessive dust, salinity, or metal powde

Operation or storage in places with vibration or shock affecting the G3J. Operation or storage in places with water, oil, or chemical sprayed on the G3J.


## Use alcohol to clean the G3J. Do not use paint thinner to clean the G3J.


Doing so will damage or discolor the surface of the G3J Do not drop the G3J or shock or vibrate the G3J excessively


#### Doing so may result in damage to the G3J or cause G3J to malfunction

an electric shock may occur or the G3J

Repairs and Modification Do not disassemble, repair, or modify the G3J, otherwise









# ■Example of Wiring Connections

DC12~24

G3J





Note: These dimensions are for the G3J-□217BL

- ●Note 1: The B form contact of Thermal Relay should be connected to Terminal 2(+)or commo line (-).It causes a contact failure to connect to Terminal 1.
- Note 2: In case of the permissible load of Thermal Relay's auxiliary contacts lower than Input current of G3J (S), Bleeder Resistance should be used in parallel to the input.

Safty standerd approval

- G3J-S : IEC947-4-2 From2


·Rated impulse withstand voltage — 4kV 1.2×50 μs

10A quick active fuse. In case of shortcircuit, the unit can be damaged. AWG 16

# Usage of G3J to raise a reliability

Thank you for purchasing an OMRON product.

Make sure that signals input into the SSR Units are proper if the SSR Units are applied to the forward and reverse operation of a three-phase



1.Be sure to use a fuse or nonfuse breaker to protect the G3J. 2.Be sure that the interal between forward

and reverse operations is at least 100 ms. If the G3J is turned ON by noise input, short-circuiting between phases will result. In order to prevent this, insert the protective resistor R

[ Example : G3J-205BL ]

The G3J-205BL withstands an inrush current of 150Apeak.  $R > 200 V \times \sqrt{2} / 150 A = 1.9 \Omega$ Considering the circuit current and weld time,insert the prtective resistance into the side that reduces the current consumption.

Obtain the consumption power of the resistance from the following

 $: I^2 R \times Safety factor$ 

( I = Load current, R = Protective resistance Safety factor = 4) 2Ω 100W 1. 5 kW

G3J-211BL (-2 <sup>1</sup> Two G3J-S or G3J-T Units cannot be used together in reversible opeation. <sup>1</sup>

●G3J-S or G3J-T with a Reversible Contactor

with Built-in Mechanical Interlock Function

1.Be sure to use a fuse or nonfuse breaker to protect the G3.I

starts operating, the soft-start function may not of the sequential circuit according to the application

●FMI

current to continue rotating the motor during ramp-down time setting even after the control signal of the G3J-T is turned OFF. Therefore, a time lag is required between the time when the G3J-T 2.Be sure that the interval between forward and stops operating up to the time when the reversible reverse operations is at least 100 ms.

3.Be sure to apply the input signal of the G3J-S

the G3J-T isadjustable up to approximately 25s max. after the reversible contactor starts operating. therefore, set the time lag to 25s in the initial sequence If the input signal is applied before the contactor during the adjustment stage. Adjust the time lag



This is a class A product. In residential areas it may cause radio interference. In which case the user may be required to take adequate measures to reduce interference

### **CONDITIONAL PROPOSAL**

At the following condition, it should be considered to use the product correctly on the rating and characteristics. Further, any fail-safe is required for safety solution and any information is expected

- (1) In case of using at the condition and circumstance not described on the manual or catalogue (2) At Nuclear control, Train, Airplane, Viecle, Burner control, Hospital equipment, Amusement, Safety machine and so on
- (3) In case of influence to human life and their property.

