INSTRUCTION MANUAL

Thank you for purchasing this OMRON product. This manual primarily describes precautions required in installing and wiring the timer. Before operating the product, read this manual thoroughly to acquire sufficient knowledge of the product. Keep this manual for future reference.





Karasuma Nanajo, Shimogyo-ku, Kyoto 600, Japan OMRON Corporation 0617623-76

Precautions on Safety

Definition of Safety Indications

1. Remove the battery compartment lid on the rear panel of 4.Two time setting brackets are the timer and place the battery attached as an accessory

■ HINTS ON CORRECT USE

into the compartment. Push here from above Then apply ogwer to the timer. Be sure to Assembly the timer. insert the battery : otherwise, Power indicator flashes even when power is spalled to it.

2. When installing the battery, be sure to correctly connect the onles of battery to the terminals as inscribed inside the compartment. Before applying power to the limer, reattach the compartment lid.

3.Rotate the center knob in the errow direction (i.e., clockwise) to set the time. The present time can be set in 30-minute units, (For example, 11:30, SUN. as shown in the figure.) Do not rotate the knob counterclackwise.



provided : QN (gold) and QFF ON time (silver). Be sure to use the setting correct bracket and securely insert it in the groove of the

Atternately set the ON and OFF time setting brackets

5. After setting the time, reattach the transparent covered the front pane

. Rotate the operation selector (with indicator) clockwise. cently pushing it.

8. When the manual switch of the timer having an SPOTE contact is lurned OFF, terminals 4 and 5 as well as 5 and 6 are coaned and thus no output is produced between either nair of these terminals. When the manual switch is turned ON, terminals 4 and 5 are closed and an output is produced across them tterminals 5 and 6 remain



When the manual switch is returned to AUTO position from the ON or OFF position, check the status of the contact with the indicator of the operation selector. If the desired contact status has not been set, rotate the operation salactor elockwise to set the desired contact

10. Do not dron or roughly handle the timer.

. When the surface of the timer is spoiled wipe it with a clean cloth moistened with soap weter or alcohol. Do not use benzene or thinner and prevent the timer from being exposed to insecticide soray. These substances cause the surface of the timer to become dull, crack, or the inscriptions to be erased.

12. Avoid using the timer in the locations subject to o direct sunlight

Function

Indicates the ON/OFF status of the


orgindroos or water solach



■ DIMENSIONS







of the timer. H2F-WMF (3) When wiring can be performed from the back of the panel, insert the timer into the hole

TOWER FAILURE COMPENSATION

Since this timer has a power failure compensation

function which enables the continuous operation

1.Power failure compensation function

adenter

Panel 12 MAKE

(1) Hook part @of the exclusive

adapter to a corner of the cutout

hole on the panel and push the

adapter in the arrow A direction.

Then oush the part 8 of the

(2) Place the battery attached as

an accessory into the battery

compartment on the rear panel

and cently secure the timer with

adapter into the hole.


the mounting screws.

Flush mounting (H2F-WM,-WMC)



■ MOUNTING METHOD AND DIMENSIONS

(5) If wiring cannot be performed from the back of the panel (because of obstacles such as a wall or a pillar). perform the wiring as shown, before inserting the timer into the panel as shown. Then rotate the timer on the axis indicated as C to insert it into the panel. Secure the pmer in the same manner as step (2) with the mounting



Note: When removing the mounted timer from adaptor, replace the nuts to the original positions (hooked at adaptor arm) in order to correctly mount the timer again

Two M3 teo

Surface mounting (H2F-WMF.-WMFC)

Track mounting (H2F-WMF.-WMFC)



To mount the timer on the surface of a panel or track first loosen the screw at the center of the terminal cover to remove the cover. Then perform the wiring of the terminals After wiring, be sure to reattach the terminal cover and secure it with the mounting screw.



■ CONNECTIONS

TYPE NAME AND NOMENCLATURE

H2F-WM.-WMF Terminals (f) and (6) are vacant.

Motor circuit

Power

H2F-WMC, WMFC

Terminal (1) is vacant

Note:Connect an independent power

source to the load.

■Safety Indications

△WARNING

A WARNING

Never touch or disassemble the terminals. Flectric Shock Hazard.




Incorrect product

cause serious in-

handling may

jury or death.

Motor 1.2V	Type	Rated input voitage	Mounting style	Contact form	Contr
Power circuit	H2F-WW	MC MF 100 to 240 VAC	Flush mounting	SPST- NO	250 V 15 A (resist load)
	H2F-WMC			SPDT	
99990	H2F-WMF		Surface mounting Track mounting	SPST- NO	
100 to 240 VAC	HZF-WOMFC			SPDT	



H2F-WM

H2F-WMF -WMEC

Operation selector control output; rotating the h Indicator knob clockwise turns the control outout ON/OFF VAC Two time setting brackets are provided: Time setting brackets ON time setting bracket and OFF time setting bracket. They turn the control output ON or OFF at the specified time. Holds time setting brackets and indicates the time in every 15 minutes. Manually rotates the dial and indicates the present time in 1-munitue units. Secures the timer with M3 screws. Mounting hole Stores the time setting bracket not in bracket storage compartment AUTO: Produces the control output as specified by the time setting bracket position on the dial. ON: Normally turns ON the output irrespective of the time setting bracket position on the dial. GFF: Normally turns OFF the output irrespective of the time setting bracket position on the dial. Lights when power is applied and ower indicator indicates that the timer is in operation

of the internal clock circuit, it is not necessary to adjust when a power failure occurs and it is within the rated power failure compensation time. The timer can control the output as usual, however the power indication turns off during that period. 2.Power failure compensation time The rated power failure compensation time is 180 hours with the battery incorporated. Though the battery is fully charged, if it were deteriorated by natural discharge etc., the compensation time 180 hours is guaranteed after 72 hours energization continuously from when the battery is installed into the timer. And when the battery has been fully discharged, the timer might not operate as soon as the power is applied. In this case, set the present time after more than 3 minutes energization. 3.Battery replacement As the hattery life is approx, 3 years, replace the

battery as soon as possible after using 3 years or

4.Battery recycling

Removed Nickel-cadmium battery when abolishing the time switch and the battery whose life is ended should be recycled since it is precious resources.

■ OPERATION

1. Firmly insert the ON/OFF time setting bracket to the desired time setting groove. However, do not insert it in a groove within ±15 minute distance from the dial propose that indicates the present

(4) Perform the wiring from the back of the panel

2.After the time setting bracket is fixed and with the power and load connected to the timer, rotate the knob in the arrow directon. Turn the dial one complete rotation to check if the control output is turned ON/OFF in accordance with the setting of the time setting bracket on the dial.

3.Rotate the knob in the arrow direction and set the desired time according to 3 in Hints on correct use

4. Now start the operation of the timer.







■ TIMING CHART

Example



With the above setting, the timing-chart will be as



2、時刻合わせのときは、中央 部ツマミを矢印の方向(時 計画転方向) にまわしてく ださい。30分単位で現在時 翅をセットすることができ ます。(たとえば図に承しま す時刻は日曜日の11時30分



ありますので、セットされ る場合はよく確認のうえ、ダイアルに確実に差し込ん でください。最小セット開脳は2時間ですので、無理 に1時間単位にセットすることは絶対にしないように 建業してください。

4、セット子はON用(金色)・OFF用(銀色) を交互にセッ トしてください。

正しい使い方

ツマミ

5、セットのあと、透明カバーを 必らずしめてください 6. ON-OFF表示付動作切換フ

マミを囲わす場合は、軽く押 しぎみに右方向 (時計回転方) 遅いくまわしてください。 接点構成が10の場合、マニ

ュアルスイッチをOFF状態に LCタイプのマニュアル スイッチ OFF A.M. しますと、第一第一章端子と # OFF状態となり、どの電子

からも出力しません。マニュアルスイッチをON共態 にしますと、第一意識子師がONとなります。15~5 期はOFFとなります。)

8、マニュアルスイッチをONまたEOFFからAUTOにも とした場合は、接点状態を「ON-OFF表示行動作の終 フマミ でご確認ください ご希望の接点状態でないと きは、「ON-OFF表示付動作切換ツマミ」を行う向に まわして、ご希望の接点状態にして、ご使用ください。 9. 落としたり、乱暴な取扱いは、さけてください

10. 外弦の汚れのひどいときは石ケン水かアルコールでふ きとってください。 ベンジン、ダンナーなどであいた り、殺虫剤がかかったりしますと、くもり心び割れてご言れなご を生じる原因となりますので、絶対に避けてくださ!・


11 ホコリや混気の多い場所、直射日光のあたる場所、気 外などの直接雨や水流のかかる場所でのご使用は避け てください。やむをえずご使用になる場合は保護のた め箱などの中に取り付けてご使用ください


■ 外形寸法

■ 取付方法と取付寸法

H2F-WM. -WMC







体の裏面にある電池ボックスに セットしてください。 23/パネル背面から配線できる場合 は、タイムスイッチ本体を挿入 1.. 存属ネジにて、かたつきが たくたるまで軽く締め付けてく ださい。

Ni-Cd

埋込取付(H2F-WM、-WMC) (H2Fネル質面より危険して) 11211


5)パネル背面から配保できな い場合。(株) 住埋込など) パネル前面で配採し、C部 を支点として回転状態に得 1 认为12 运制煤品付银币系 パネルカット寸法 少にて固定していたまい




注:本体を取りにすした場合にアダプタのナート部を行列 カバーをモニ状態にもどしてジ締 教練(アダフタ雑部にファク間定)にもとしてご使用 が固立をして ご使用したさい。 ください。

表面取付 (H2F-WMF, --WMFC) 61.5.3 2M12 7

DIN レール取付 (H2F-WMF, -WMFC)




合の配成は、電子ウバー中央部の **ネシルこくのカバーを開いて配線** してください。 配線後は必て端子



■ 接続図

H2F-WM. -WMF ①、⑥はあき端子です。



H2F-WMC -WMFC ①はあき端子です。

注 負荷には負荷用電源を接続してください。

■ 形式名・各部の名称

● 警告表示

オムロン株式会社

△警告

形 H2F-WM, -WMF

モータ式ウイークリータイムスイッチ

取扱説明書

オムロン製品をお買い上げいただきありがとうございます。

この初島を安全に任じく使用していただくために、お願いに

なる前にこの取扱説明書をお読みになり、十分にご理解して

端子に触れたり、分解しない でください。感覚の恐れがあ ります。




ご使用に際してのお願い

次に示すような条件や環境で使用する場合は、定格、 機能に対して余裕を持った便い方やフェールセイフな どの安全対策へのご配慮をいただくとともに、当社賞 業担当者までご相談してくださるようお難いいたしま T_

全取扱説明書に記載のない条件や環境での使用 窓原子力制御・鉄道・航空・車両・燃焼装置、医療機 器・娯楽機械・安全機器などへの使用 ②人命や財産に大きな影響が予測され、特に安全性が


要求される用途への便用

| 形 式 名 | 定格入力電圧 取付方法 | 接点構成 | 制卸出力 H2F-WM 1 c AC 581154 HPF-WMC (高校)(有) H2F-WMF ·五面取得 l a l c ·DINE - · REF H2F-WMFC



H2F-WM -WMC H2F-WMF -WMFC





■ 停電補償について

H2F-WMF, -WMFC

キタイムスイッチは電源電圧の停電時においても、内蔵 の電池によって内部時計回路が計時歩進する停電頻低機 院と有していますので、電池が有効にはたらく停電補償 時間以内の停電ならば時刻再調整の必要は有りません。 出力の制御も通常とおりおこないます。ただし動作表示 ランフは消却します。

2. 经电桶低時間

冷電中は付属の電池を内蔵することにより180時間以上 ∴砂定を補償します。

ただし、付属の電池はフル光電されたものですが、ガー 自然放電等で電池能力が低手している場合は、180時間以 上の停電補償機能は電池を本体に収めたのち、72時間建 **松通電された場合に保証されます。なお電池が完全放電** している場合、電源を印加してもすぐに動作しないこと があります。この場合3分以上通電後現在時刻をセット してください。

3. 電池交換

心波の寿命は、約3年ですので、ご使用後3年以上経過 しましたら、できるだけ早く交換してください。電池は 弱売のオムロン 形 Y 92 S - 22 をお使いください。本タイ ムスイッチをお買い上げいただいた販売店にご住文くだ B 1 4 5

4、電池のリサイクル

オムロン科学組み出ばニッケル・ カドミウムボ泡です。身命にな たニッケル・カドミウム追他およ び機器を定発する際に取り外した ニッケル・カドミウム電池は青毛 内帯器ですので、リサイクル操り 害まだは本タイムスイッチをお買 いわけいただいた販売店にお持ち

17150 なお、取り外した電池は、端子部 キテープ等で絶縁し、電解液から 体は触れないようボリ教等に入れ 水のかからない場所に保管くたう 51.

ミ・ニステッチ裏面の電池カバーを取りはずし付属の **事点をセートしてくてきい。 進池の操作は道池ボック** で出ること示しています。セット後はカバーを元の状 他に対してください

ー FON-OFFをお望みの時刻のダイアル溝に確 T. Fa . あんでくろさ、 ただし現在時刻位置のダイ - マミ溝から主2時間に内のマイアル溝にはセット子を とし込まないで、中央部のソマミを廻わして現在時刻 !買った少し移動させてからセット子を着し込んでく

モニテム取り付けが終りましたら、電源および負荷 を接続した状態で、中央部ツマミを矢印の方向にまわ し、マミアルを上回転させて、セット子をセットした。 プロマッニとおり、ON-OFF動作表示」が切換わるこ とを確認してください。

1、中央部ツマミを矢印方向にまわして、 正しい使い方 の2項の要額で現在時刻をセットしてください。

5. 以上で動作を開始します

■ 操作方法





[例]

■ タイムチャート

上図のセットにおけるタイムチャートは次のようになり ます。(現在時刻は月曜日の2時を示しています。)



